Horn Observation Check List

- Horn & can antenna
- Base stand
- LNA
- SMA cable, female to female
- Airspy
- Airspy to computer micro-USB cable
- Computer with Gnuradio spectrum_w_calibration.grc file